

CIMS INTERNATIONAL N.V.

Container, cargo & marine surveyors


ON HIRE/CONDITION INSPECTION REPORT

CONTAINER NUMBER GASH 554005.7.		CLIENT NAME TRANSPO.		SURVEY DATE 10/1/01		LOCATION ZOOM		DEPOT DAMI	
TANK TYPE IM105.	MANUFACTURER DHE	SERIAL NO.	ISO TYPE 22T6	TANK 24540	MAX 36000	PAYLOAD	TARE 9000.		
FIRST TEST 6/97.	LAST 2 1/2 YR TEST 6/00	LAST 5 YR TEST 6	NEXT TEST DUE		CSC 6/02	MAWP	TEST		
STWP	ST PRESS.	TANK HEAD MAT		TANK SHELL MAT		HEAD THICKNESS	SHELL THICKNESS		

GENERAL CONDITION FRAME:

CLADDING:

PAINT:



DAMAGE CODES

- B Bent C Cut D Dent CR Cracked EZ Exist. Rep. H Hole
- COR Corrosion L Loose SC Scratched M Missing ST Stained IR Improper Repair

COMPONENT CHECK LIST	FITTED		COMMENTS
	Y	N	
MARKINGS AND PLATES			
Data plates	✓		
Owners plate	✓		
Manufacturer's plate	✓		
CSC plate	✓		
Custom approval plate	✓		
Prefix number	✓		
IMO/DOT E number	✓		
Country code	✓		
Owner label	✓		
AAR 600	✓		
CTC impact approval	✓		
Weight / volume decals	✓		

TANK CONTAINER NO. : ASLI 544005.7

COMPONENT CHECK LIST	FITTED		COMMENTS
	Y	N	
EXTERNAL ACCESSORIES			
Front ladder		✓	
Rear ladder		✓	
Document. Box/Cap/Gask/Chain	✓		
Outlet Cap/Blank/Gask/Chain	✓		Size <u>Flanged</u> . <u>ALU/SS</u> + cover. Tie pin is bolt.
Bottom outlet valve/gaskets	✓		MFR FV/ Butterfly/Ball
Footvalve		✓	MFR FV/
Remote foot control	✓		<u>steel cable</u>
Steam Tubes/Cap/Gask/Chain		✓	Size ALU/SS
Thermometer	✓		MFR <u>C-F</u>
Walkway		✓	
Manhole Protection Cover		✓	
Spillbox		✓	
Manlid / Seal	✓		SWR/PTFE
Manlid swing bolts	✓		<u>4-8-8</u> <u>Bolted</u>
Dipstick		✓	
Calibration Chart	✓		<u>DENTED</u> .
Safety Dev.Prot.Cover/Spillbox	✓		
EXTERNAL ACCESSORIES			
PV Relief valves 1	✓		MFR EX/ <u>Conf.</u> Ser Vac Press
PV Relief valves 2			MFR FV/ Ser Vac Press
Pressure Gauges	✓		MFR <u>2x</u> Range
Flame Traps on P/V Rel. Val.	✓		
Air Line Cap/Gasket/Blank/CH		✓	Size ALU/SS
Air Line Valve/Gasket/Gauge		✓	MFR Range
Top Disch. Prot. Cover/Spillb.		✓	
Top Disch. Valve		✓	MFR Butterfly/Ball
Top Disch. Blank/Gas.		✓	
Top Operated Int. Footvalve		✓	
Tir strips bottom/top	✓		
INTERNAL CONDITION			
Cleaned / Dry	✓		<u>Under nitrogen pressure</u>
Discoloured			
Rusted			
Corroded			
Pitted/Lamination Pitting			
Thermometer probe			
Valv. Clean fm. Moist/Res.			
Siphon tube			
Footvalve			
Bursting discs	✓		MFR Range
Cleanliness certificate			

REMARKS : See PHOTO
Internal condition not checked due to nitrogen blanked.

<input checked="" type="checkbox"/> Accepted	Surveyor's Name <u>[Signature]</u>
<input type="checkbox"/> Rejected	











